

```

<?xml version="1.0" standalone="yes"?>
<TRACS_IMPORT>
  <ALCOTEST_VALUES>
    <SERIAL>ARAF-0084</SERIAL>
    <IP_ADRESS>10.81.186.159</IP_ADRESS>
    <DATE>12/31/2019</DATE>
    <TIME>04:18AM</TIME>
  </ALCOTEST_VALUES>
  <CALCHECK_1>
    <CAL_MESSUNG_2_MESSUNG_ERROR>0</CAL_MESSUNG_2_MESSUNG_ERROR>
    <CAL_MESSUNG_2_IR_AAK_NULLWERT_1>0.00</CAL_MESSUNG_2
_IR_AAK_NULLWERT_1>
    <CAL_MESSUNG_2_IR_AAK_MESSWERT>0.09</CAL_MESSUNG_2
_IR_AAK_MESSWERT>
    <CAL_MESSUNG_2_EC_AAK_MESSWERT>0.09</CAL_MESSUNG_2
_EC_AAK_MESSWERT>
    <CAL_MESSUNG_2_IR_AAK_NULLWERT_2>0.00</CAL_MESSUNG_2
_IR_AAK_NULLWERT_2>
    <ID_BLANK_TIME_BEFORE_2>04:03:19AM 12/31/2019
</ID_BLANK_TIME_BEFORE_2>
    <ID_TIME_START_BLOW_2>--:--:-- --/--/-----
</ID_TIME_START_BLOW_2>
    <ID_TIME_MEAS_2>04:03:56AM 12/31/2019</ID_TIME_MEAS_2>
    <ID_BLANK_TIME_AFTER_2>04:04:35AM 12/31/2019
</ID_BLANK_TIME_AFTER_2>
  </CALCHECK_1>
  <SUBJECT_TEST>
    <PROB_MESSUNG_2_MESSUNG_ERROR>0</PROB_MESSUNG_2
_MESSUNG_ERROR>
    <PROB_MESSUNG_2_IR_AAK_NULLWERT_1>0.00</PROB_MESSUNG_2
_IR_AAK_NULLWERT_1>
    <PROB_MESSUNG_2_IR_AAK_MESSWERT>0.23</PROB_MESSUNG_2
_IR_AAK_MESSWERT>
    <PROB_MESSUNG_2_EC_AAK_MESSWERT>0.22</PROB_MESSUNG_2
_EC_AAK_MESSWERT>
    <PROB_MESSUNG_2_IR_AAK_NULLWERT_2>0.00</PROB_MESSUNG_2
_IR_AAK_NULLWERT_2>
    <PROB_MESSUNG_2_BLAS_FEHLVERSUCHE>3</PROB_MESSUNG_2
_BLAS_FEHLVERSUCHE>
    <PROB_MESSUNG_2_BLAS_VOLUMEN>1.7</PROB_MESSUNG_2
_BLAS_VOLUMEN>
    <PROB_MESSUNG_2_BLAS_ZEIT>10.0</PROB_MESSUNG_2_BLAS_ZEIT>
    <ID_BLANK_TIME_BEFORE_3>04:12:07AM 12/31/2019, 04:05:42AM
12/31/2019, 04:09:37AM 12/31/2019, 04:10:39AM 12/31/2019
</ID_BLANK_TIME_BEFORE_3>
    <ID_TIME_START_BLOW_3>04:13:39AM 12/31/2019, 04:10:55AM
12/31/2019</ID_TIME_START_BLOW_3>
    <ID_TIME_END_BLOW_3>04:13:49AM 12/31/2019, 04:11:04AM
12/31/2019</ID_TIME_END_BLOW_3>
    <ID_TIME_MEAS_3>04:13:57AM 12/31/2019, 04:08:55AM
12/31/2019, 04:09:52AM 12/31/2019, 04:11:05AM 12/31/2019
</ID_TIME_MEAS_3>

```

```

    <ID_BLANK_TIME_AFTER_3>04:15:24AM 12/31/2019
</ID_BLANK_TIME_AFTER_3>
    </SUBJECT_TEST>
    <CALCHECK_2>
        <CAL_MESSUNG_3_MESSUNG_ERROR>0</CAL_MESSUNG_3_MESSUNG_ERROR>
        <CAL_MESSUNG_3_IR_AAK_NULLWERT_1>0.00</CAL_MESSUNG_3
_IR_AAK_NULLWERT_1>
        <CAL_MESSUNG_3_IR_AAK_MESSWERT>0.09</CAL_MESSUNG_3
_IR_AAK_MESSWERT>
        <CAL_MESSUNG_3_EC_AAK_MESSWERT>0.09</CAL_MESSUNG_3
_EC_AAK_MESSWERT>
        <CAL_MESSUNG_3_IR_AAK_NULLWERT_2>0.00</CAL_MESSUNG_3
_IR_AAK_NULLWERT_2>
        <ID_BLANK_TIME_BEFORE_4>04:15:25AM 12/31/2019
</ID_BLANK_TIME_BEFORE_4>
        <ID_TIME_START_BLOW_4>--:--:-- --/--/-----
</ID_TIME_START_BLOW_4>
        <ID_TIME_MEAS_4>04:15:26AM 12/31/2019</ID_TIME_MEAS_4>
        <ID_BLANK_TIME_AFTER_4>04:16:04AM 12/31/2019
</ID_BLANK_TIME_AFTER_4>
    </CALCHECK_2>
    <GENERAL_DATA>
        <ID_SERIAL_NO>ARAF-0084</ID_SERIAL_NO>
        <ID_SW_VERSION> 8321288 1.12.2</ID_SW_VERSION>
        <ID_START_TIME>04:00:28AM 12/31/2019</ID_START_TIME>
        <ID_END_TIME>04:16:54AM 12/31/2019</ID_END_TIME>
        <ID_LAST_CAL_DATE>08/02/2019</ID_LAST_CAL_DATE>
        <ID_AAK_ENDRESULT> 0.22 %BAC</ID_AAK_ENDRESULT>
        <ID_TEST_COUNTER>854</ID_TEST_COUNTER>
        <ID_MEAS_PROC>1</ID_MEAS_PROC>
        <ID_CALIBRATION_COUNTER>80</ID_CALIBRATION_COUNTER>
        <ID_ERROR_PROTOKOLL>0</ID_ERROR_PROTOKOLL>
        <ID_TEST_GAS_TYPE>2</ID_TEST_GAS_TYPE>
        <ID_TEST_GAS_INLET>1</ID_TEST_GAS_INLET>
        <ID_TEST_GAS_CONC>25.00</ID_TEST_GAS_CONC>
        <ID_TEST_CFG_SENSOR>0</ID_TEST_CFG_SENSOR>
        <ID_DATA_INPUT_ON_OFF>1</ID_DATA_INPUT_ON_OFF>
        <ID_IR_AVERAGE>21167</ID_IR_AVERAGE>
        <ID_EC_SENSOR_OFFSET>112</ID_EC_SENSOR_OFFSET>
        <ID_HOSE_TEMP>46.7</ID_HOSE_TEMP>
        <ID_IR_SENSOR_TEMP>45.3</ID_IR_SENSOR_TEMP>
        <ID_INTERNAL_DEVICE_TEMP>36.0</ID_INTERNAL_DEVICE_TEMP>
        <ID_12V_VOLTAGE>12.2</ID_12V_VOLTAGE>
        <ID_3V_BACKUP_VOLTAGE>3.3</ID_3V_BACKUP_VOLTAGE>
        <ID_MS_SW_CRC>0x6581</ID_MS_SW_CRC>
        <ID_PRESSURE_DRY_GAS>0</ID_PRESSURE_DRY_GAS>
        <ID_DRY_GAS_LOT_NO>1090299 #32</ID_DRY_GAS_LOT_NO>
        <ID_DRY_GAS_EXP_DATA>02/08/2022</ID_DRY_GAS_EXP_DATA>
    </GENERAL_DATA>
    <INPUT_VALUES>
        <UF_CASE_NUMBER>9351143</UF_CASE_NUMBER>
        <ZERO_TOLERANCE_CASE>NO</ZERO_TOLERANCE_CASE>

```

```

<TROOP>D</TROOP>
<STATION>ELBRIDGE</STATION>
<ARREST_DATE>12/31/2019</ARREST_DATE>
<ARREST_TIME>03:20AM</ARREST_TIME>
<ARRESTING_MEM_LAST>LOTITO</ARRESTING_MEM_LAST>
<ARRESTING_MEM_FIRST>NICHOLAS</ARRESTING_MEM_FIRST>
<ARRESTING_MEM_MI>J</ARRESTING_MEM_MI>
<ARRESTING_MEM_SHIELD>5436</ARRESTING_MEM_SHIELD>
<SUBJECT_LAST_NAME>PRESTON</SUBJECT_LAST_NAME>
<SUBJECT_FIRST_NAME>JEFFREY</SUBJECT_FIRST_NAME>
<SUBJECT_MI>D</SUBJECT_MI>
<SUBJECT_DOB>01/04/1962</SUBJECT_DOB>
<SUBJECT_AGE>57</SUBJECT_AGE>
<SUBJECT_GENDER>MALE</SUBJECT_GENDER>
<OPERATOR_LAST_NAME>CORNISH</OPERATOR_LAST_NAME>
<OPERATOR_FIRST_NAME>MATTHEW</OPERATOR_FIRST_NAME>
<OPERATOR_MI>W</OPERATOR_MI>
<OPERATOR_SHIELD_NO>851</OPERATOR_SHIELD_NO>
<OPERATOR_PERMIT_NO>42047</OPERATOR_PERMIT_NO>
<OPERATOR_PERMIT_EXP>09/27/2021</OPERATOR_PERMIT_EXP>
<SUBJECT_OBSERVED_20_MINUTES>YES</SUBJECT_OBSERVED_20
_MINUTES>
  <TEST_20_MINUTES_PAST_ARREST>YES</TEST_20
_MINUTES_PAST_ARREST>
  <REFUSAL_MIRANDA_READ>YES</REFUSAL_MIRANDA_READ>
</INPUT_VALUES>
</TRACS_IMPORT>

```